	Туре	Hits	Search Text	DBs	Time Stamp
1	IS&R	405	(228/121).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:00
2	IS&R	594	(228/234.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/19 17:33
3	IS&R	462	(228/235.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/19 17:39
4	IS&R	352	(228/262.1).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/19 17:43 [°]
5	IS&R	372	(228/262.5).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/19 17:46
6	IS&R	519	(228/262.51).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/19 17:46
7	IS&R	1260	(156/272.2).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 08:33
8	IS&R	501	(156/272.8).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 08:45
9	IS&R	281	(156/273.7).CCLS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 08:45
10	IS&R	2	(("6582548") or ("5178319")).PN.	USPAT	2005/10/20 10:00
11	BRS	3	("4534811" "5178319" "5337383").PN. OR ("6582548").URPN.	US-PGPUB; USPAT; USOCR	2005/10/20 09:48

	Туре	Hits	Search Text	DBs	Time Stamp
12	BRS	21	("3360849" "3577629" "3609470" "3665594" "3860405" "4610746" "4659378" "4687285" "4711521" "4793688" "4897711").PN. OR ("5178319").URPN.	US-PGPUB; USPAT; USOCR	2005/10/20 09:51
13	IS&R	2	(("4534811") or ("4610746")).PN.	USPAT	2005/10/20 10:00
14	BRS	25	("3891523" "4133723" "4192762" "4436366" "4479698").PN. OR ("4610746").URPN.	US-PGPUB; USPAT; USOCR	2005/10/20 10:01
15	BRS	50	("3304403" "3382343" "3404350" "3509317" "3608809" "3617683" "3747198" "3986767" "3997385" "4320281").PN. OR ("4534811").URPN.	US-PGPUB; USPAT; USOCR	2005/10/20 10:05
16	IS&R	3978 8	("228").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:00

	Туре	Hits	Search Text	DBs	Time Stamp
17	IS&R	1116 90	("156").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:00
18	IS&R	1219 97	("219").CLAS.	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:00
19	BRS	2659 00	S16 or S17 or S18	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:06
20	BRS	1810 0	\$19 and (bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:07
21	BRS	6431	S19 and ((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) and (laser or light)	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 11:13
22	BRS	531	\$19 and (((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) near200 (laser or light))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:23

	Туре	Hits	Search Text	DBs	Time Stamp
23	BRS	168	, -	US-PGPUB; USPAT;	2005/10/20 12:23
24	BRS	149	\$19 and (((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) near200 (laser or light)) and (discontinuous or strip\$1 or dot\$1) and (layer\$1 or substrate\$1)	US-PGPUB; USPAT;	2005/10/20 12:24
25	BRS	76	S19 and (((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) near200 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near200 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:24

	Туре	Hits	Search Text	DBs	Time Stamp
26	BRS	76	S19 and (((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) near200 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near100 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:24
27	BRS	76	S19 and (((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) near200 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near50 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:35
28	BRS	407	(((bond\$3 or solder\$3 or braz\$3) near50 (compression or pressure or force)) near200 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near50 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:36

	Туре	Hits	Search Text	DBs	Time Stamp
29	BRS	407	(((bond\$3 or solder\$3) near50 (compression or pressure or force)) near200 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near50 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:36
30	BRS	391	(((bond\$3 or solder\$3) near20 (compression or pressure or force)) near200 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near50 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:36
31	BRS	391	(((bond\$3 or solder\$3) near20 (compression or pressure or force)) near100 (laser or light)) and ((discontinuous or strip\$1 or dot\$1) near50 (layer\$1 or substrate\$1))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:36

	Туре	Hits	Search Text	DBs	Time Stamp
32	BRS	10	((((bond\$3 or solder\$3) near20 (compression or pressure or force)) near100 (laser or light)) near200 ((discontinuous or strip\$1 or dot\$1) near50 (layer\$1 or substrate\$1)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:37
33	BRS	68	((((bond\$3 or solder\$3) near20 (compression or pressure or force)) near100 (laser or light)) near200 ((discontinuous or strip\$1 or dot\$1)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:38
34	BRS	61	((((bond\$3 or solder\$3) near10 (compression or pressure or force)) near100 (laser or light)) near200 ((discontinuous or strip\$1 or dot\$1)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	2005/10/20 12:38